	CLASSIFICATION CONTROL	7
COUNTRY	Soviet some of Germany REPORT NO.	'
TOPIC_Doc	eberitz iirfield	25X1
		The sale framework reported for distance of security
EVALUATION	N See bolow PLACE OBTAINED 25X1	Price Wilderford Company and Analysis and Analysis of Expenses
	CONTENT 14 and 15 September 1950	
DATE OBTA	25X1 25X1 DATE PREPARED 11 October 1950	
REFERENCE	A Year and a second a second and a second an	
PAGES	1 ENCLOSURES (NO. & TYPE) 25X1 RETURN TO CI	٨
	LIBRARY	and the second s
		pin-rai-waniantantanian at aunimperior and
 (1		
		•
	airfield and 25 planes of the same type on the southern edge in front of the hangars. Thirty-one planes of the same type approach the field from the west about 5:15 p.m. They flew in four formatiat intervals of two to three minutes. * The formations broke up of	ions,
	front of the hangars. Thirty-one planes of the same type approach	ions, over to 20
	the field from the west about 5:15 p.m. They flew in four formatiat intervals of two to three minutes. * The formations broke up a the field and the planes landed individually at intervals of 15 seconds. Eleven planes taxied to the northern edge and 20 to the southern edge of the field. All aircraft had a weapon protruding beyond the cockpit to the rear and, except They had in-line engines, wangs slightly bent the rear, landing gear retracting rearward, tail wheel not retract	ions, over to 20 t to ctable,
(1	the field from the west about 5:15 p.m. They flew in four formatiant intervals of two to three minutes. * The formations broke up of the field and the planes landed individually at intervals of 15 to seconds. Eleven planes taxied to the northern edge and 20 to the southern edge of the field. All aircraft had a weapon protruding beyond the cocknit to the rear and, except They had in-line engines, wings slightly bent the rear, landing gear retracting rearward, tail wheel not retract and antenna rod forward of the cockpit. 2. The hangars were closed. Yellow and rod flags marked the directic landing. The spur track was slightly rusty. No notor vehicles were	ions, over to 20 t to ctable, on of re
X1 X1 X1 X1 X1	the field from the west about 5:15 p.m. They flew in four formations at intervals of two to three minutes. * The formations broke up of the field and the planes landed individually at intervals of 15 is seconds. Eleven planes taxied to the northern edge and 20 to the southern edge of the field. All aircraft had a weapon protruding beyond the cockpit to the rear and, except They had in-line engines, wings slightly bend the rear, landing gear retracting rearward, tail wheel not retract and antenna rod forward of the cockpit. 2. The hangars were closed. Yellow and rod flags marked the directic landing. The spur track was slightly rusty. No noter vehicles were seen. There was no flying up to 6 p.m. 3. Then riding past the field at 9:30 a.m. on 15 September 1950, 53 single-engine, low-wing monoplanes were seen on the southern edge about 60 aircraft of the same type on the northern edge. * Truck	ions, over to 20 t to 20 t to ctable, on of re e and ved at on was

CONFIDENTIAL